

TORO REELMASTER 200 AND 2000 SERIES

- Replace engine oil.
- Replace air filter.
- Remove debris from around exterior of the cylinder fins & air intake screen (air cooled only)
- Replace spark plugs (air cooled only)
- Replace fuel filter & inspect all fuel lines.
- Adjust carb idle.
- Load test battery, clean battery cables, check electrolyte level - adjust if needed.
- Check charging system.
- Inspect operation of all gauges, indicator lights, & safety switches (replace any non-working switches at additional charge - mandatory).
- Replace hydro oil filter (change oil or adjust level if needed.)
- Inspect all hydro hoses & fittings for leaks, clean oil cooler.
- Check operation of traction linkage for excessive play & adjust neutral.
- Inspect hydro pump, wheel drive motors, & reel motors for leaks.
- Inspect parking brake for proper operation.



- Inspect electric PTO clutch, adjust for proper gap clearance (if applicable).
- Inspect jackshaft pulley assembly.
- Check for worn/damaged belts & tensioners. Adjust PTO, reel, & hydro pump drive belts for proper operation.
- Inspect cutting unit pull frames for correct alignment.
- Inspect bushings in pull frame.
- Adjust steering linkage (if applicable).
- Lubricate all grease fittings.

Recommended Services Done by Request at Additional Cost

- Perform compression test
- Flush cooling system – 1,000 hour intervals

Please notify us ahead of time of any specific problems you're having with your unit.

Based on all inspections, if additional work is required, you will be notified with a repair cost estimate.

Traction Units - 3.5 hours plus parts & lubricants (Reels – call)



TAKE ADVANTAGE OF THE REINDERS WINTER SERVICE PROGRAM AND RECEIVE TERMS OF MARCH 31, 2009 INVOICING AND 20% OFF LABOR FOR THIS AND ANY OTHER REPAIRS.



Reinders
Solutions & Supplies
for the Green Industry

CHICAGO, IL
1-866-655-8335
847-678-5555

MILWAUKEE, WI
1-800-785-3307
262-786-3307

APPLETON, WI
920-788-0200

MADISON, WI
608-244-0200

www.reinders.com