

# Reinders

2011-2012

## WINTER SERVICE PROGRAM

Deferred  
payment until  
March 31, 2012

15% OFF  
LABOR



**TORO**<sup>®</sup>

Our Milwaukee area location is moving to:

W227 N6255 Sussex Road  
Sussex, WI 53089

Our EETC Certified Technicians can  
work on most makes of equipment.  
Call us for pricing on various brands.

*On-site service contracts are available.*

### EQUIPMENT SERVICE LOCATIONS

**CHICAGO, IL**  
1-866-655-8335  
847-678-5555

**MILWAUKEE, WI**  
1-800-785-3307  
262-786-3307

**APPLETON, WI**  
920-788-0200

**MADISON, WI**  
608-244-0200

[WWW.REINDERS.COM](http://WWW.REINDERS.COM)

# 2011-2012 TURF EQUIPMENT SERVICE PROGRAM

Let Reinders Turf Equipment Technicians do your winter service work. Our factory trained turf equipment technicians will put your turf equipment in top shape in time for the spring season. Please call any Reinders Equipment Service Center and we will be glad to e-mail or fax you information on the specific equipment you wish to have serviced. We can also set up a time for pick up of your equipment if you so desire. Remember that all of the programs we offer can be customized to fit your needs.

For qualifying parts you will receive Toro Performance Parts Pricing. In addition, you get **March 31, 2012 dating** on all service invoices. Customer must have a current open account.

You will receive a **15% discount** off the regular hourly rate. Cleaning your equipment will be charged at a rate of \$34.00 per hour.



**Due to our limited amount of indoor storage, we cannot guarantee that your equipment will be kept inside once the winter service is completed. We ask that you take delivery or pick up your equipment as soon as possible once the service is done.**

Due to liability reasons a unit will be returned with the interlock system in operating condition. It is a federal law which we must follow, and is for your safety. Additional charges will be added for this repair.

## TO BETTER SERVE YOUR NEEDS, WE ASK YOUR COOPERATION ON THE FOLLOWING:

1. Please make note of any special service problems that we can solve for you. Maintenance items such as filters and blades will automatically be replaced unless you notify us when you call.
2. If you plan on having the Reinders fleet pick up your equipment, you must have the gang mowers out of the transport frames. Someone must also be present to assist our drivers in the loading of all equipment.
3. Due to service volume, reels sent in for sharpening after January 31, 2012 cannot be guaranteed by Spring.
4. This winter service program begins November 1, 2011 and will end March 31, 2012.



## CALL THE TURF EQUIPMENT SERVICE CENTER NEAREST YOU

### MAIN LOCATIONS:

#### MILWAUKEE, WI (SUSSEX)

W227 N6255 Sussex Rd.  
1-800-785-3307  
262-786-3307  
Fax: 262-786-4064

Service Director:  
JERRY KIENAST  
jkienast@reinders.com

Shop Foreman:  
JASON DIBB

Service Writer:  
ERIN MUDGETT

#### CHICAGO, IL (FRANKLIN PARK)

3816 Carnation St.  
1-866-655-8335  
847-678-5555  
Fax: 847-678-5511  
or 847-233-0082

Service Manager:  
BRIAN HEDGES  
bhedges@reinders.com

Shop Foreman:  
JEFF CHOLEWA

Service Advisor:  
RICK TUCKER

### STORE SERVICE LOCATIONS:

APPLETON, WI  
900 Randolph Drive  
920-788-0200  
Fax: 920-788-7190

MADISON, WI  
4217 Nakoosa Trail  
608-244-0200  
Fax: 608-245-9435

[www.reinders.com](http://www.reinders.com)



**TAKE ADVANTAGE OF THE REINDERS WINTER SERVICE PROGRAM  
AND RECEIVE TERMS OF MARCH 31, 2012 INVOICING  
AND 15% OFF LABOR FOR THIS AND ANY OTHER REPAIRS.**



# TORO REELMASTER 200 AND 2000 SERIES

- Replace engine oil.
- Replace air filter.
- Remove debris from around exterior of the cylinder fins & air intake screen (air cooled only).
- Replace spark plugs (air cooled only).
- Replace fuel filter & inspect all fuel lines.
- Adjust carb idle.
- Load test battery, clean battery cables, check electrolyte level - adjust if needed.
- Check charging system.
- Inspect operation of all gauges, indicator lights, & safety switches (replace any non-working switches at additional charge - mandatory).
- Replace hydro oil filter (change oil or adjust level if needed).
- Inspect all hydro hoses & fittings for leaks, clean oil cooler.
- Check operation of traction linkage for excessive play & adjust neutral.
- Inspect hydro pump, wheel drive motors, & reel motors for leaks.
- Inspect parking brake for proper operation.



- Inspect electric PTO clutch, adjust for proper gap clearance (if applicable).
- Inspect jackshaft pulley assembly.
- Check for worn/damaged belts & tensioners. Adjust PTO, reel, & hydro pump drive belts for proper operation.
- Inspect cutting unit pull frames for correct alignment.
- Inspect bushings in pull frame.
- Adjust steering linkage (if applicable).
- Lubricate all grease fittings.

## Recommended Services Done by Request at Additional Cost

- Perform compression test
- Flush cooling system – 1,000 hour intervals

*Please notify us ahead of time of any specific problems you're having with your unit.*

*Based on all inspections, if additional work is required, you will be notified with a repair cost estimate.*

**Traction Units - 3.5 hours plus parts & lubricants (Reels – call)**



**TAKE ADVANTAGE OF THE REINDERS WINTER SERVICE PROGRAM AND RECEIVE TERMS OF MARCH 31, 2012 INVOICING AND 15% OFF LABOR FOR THIS AND ANY OTHER REPAIRS.**



**Reinders**  
Solutions & Supplies  
for the Green Industry

CHICAGO, IL  
1-866-655-8335  
847-678-5555

MILWAUKEE, WI  
1-800-785-3307  
262-786-3307

APPLETON, WI  
920-788-0200

MADISON, WI  
608-244-0200

[www.reinders.com](http://www.reinders.com)

# TORO GROUNDMASTER AND OTHER RIDING ROTARIES 52" - 88"



- Replace engine oil & filter.
- Replace air filter.
- Adjust valve clearances & install new valve cover gasket.
- Replace spark plugs & wire set, breaker points, condenser, rotor, distributor cap (if applicable).
- Replace fuel filter, clean screen in fuel pump, & check fuel lines.
- Adjust oil level in governor (replace if needed).
- Check engine high & low speeds.
- Check all engine belts & adjust to proper tension (advise if replacement is needed).
- Clean radiator exterior & inspect all hoses for wear.
- Change coolant & fill to proper level.
- Test battery condition w/load test, clean battery cables, & check electrolyte level - adjust as needed.
- Check charging system.
- Inspect coupler between engine & hydrostat for damage or wear.
- Replace hydrostatic transmission oil & filter.
- Inspect hydrostatic transmission for leaks.
- Adjust hydrostat for neutral.
- Inspect traction pedal friction wheel.
- Replace fluid in cutter deck gearbox.
- Adjust cutter deck drive belt tension.
- Adjust PTO drive system, including PTO brake.
- Check cutter deck bearing spindles.
- Replace blades.
- Check for worn caster wheels & bearings.
- Inspect front drive axles.
- Clean & adjust brakes, brake cables, & inspect parking brake for proper operation.
- Remove rear wheel bearings, clean & repack, install new grease seals, & reinstall.
- Torque all wheel fasteners.
- Check tire pressure and adjust if needed.
- Lubricate all grease fittings.
- Check PTO fork.
- Inspect all safety switches (replace any non-working switches at additional charge - mandatory).
- Check engine mounts.

## Recommended Services Done by Request at Additional Cost

- Perform compression test
- Calibrate Injectors - 1000 hour intervals

*Please notify us ahead of time of any specific problems you're having with your unit.*

*Based on all inspections, if additional work is required, you will be notified with a repair cost estimate.*

**AIR COOL - 8 hours, WATER COOL - 8.9 hours, DIESEL - 9.8 hours plus parts & lubricants  
(Units with cabs may be more, please ask)**



**TAKE ADVANTAGE OF THE REINDERS WINTER SERVICE PROGRAM AND RECEIVE TERMS OF MARCH 31, 2012 INVOICING AND 15% OFF LABOR FOR THIS AND ANY OTHER REPAIRS.**



**Reinders**  
Solutions & Supplies  
for the Green Industry

CHICAGO, IL  
1-866-655-8335  
847-678-5555

MILWAUKEE, WI  
1-800-785-3307  
262-786-3307

APPLETON, WI  
920-788-0200

MADISON, WI  
608-244-0200

[www.reinders.com](http://www.reinders.com)

# TORO GROUNDMASTER 4000-D AND 4100-D



- Replace engine oil & filter.
- Replace fuel filter.
- Replace water separator.
- Replace air filter.
- Replace hydro oil & filter.
- Replace coolant & clean radiator fins.
- Replace blades.
- Test battery, clean battery terminals.
- Test charging system.
- Inspect all belts & adjust as required.
- Inspect all hoses.
- Check neutral point for creep & adjust if needed.
- Inspect all safety switches (replace any non-working switches at additional charge – mandatory).
- Inspect for fluid leaks.
- Inspect cutting deck for worn belts, rollers, casters, & spindles.
- Check tire pressure & adjust if needed.
- Lubricate all grease fittings.
- Check and adjust the fan and alternator belt.
- Inspect 4WD for leaks & pivot play.
- Change the planetary gear oil.
- Replace rear axle fluid.
- Check all deck and wing pivot points.
- Check wing deck switches and clean out debris.
- Check fan clutch for leaks.
- Adjust parking brake.

## Recommended Services Done by Request at Additional Cost

- Perform compression test
- Recondition radiator – 1,000 hour intervals
- Adjust the valves – 800 hour intervals
- Calibrate Injectors - 1,000 hour intervals

*Please notify us ahead of time of any specific problems you're having with your unit.*

*Based on all inspections, if additional work is required, you will be notified with a repair cost estimate.*

**5.5 hours plus parts & lubricants**



**TAKE ADVANTAGE OF THE REINDERS WINTER SERVICE PROGRAM AND RECEIVE TERMS OF MARCH 31, 2012 INVOICING AND 15% OFF LABOR FOR THIS AND ANY OTHER REPAIRS.**



**Reinders**  
Solutions & Supplies  
for the Green Industry

CHICAGO, IL  
1-866-655-8335  
847-678-5555

MILWAUKEE, WI  
1-800-785-3307  
262-786-3307

APPLETON, WI  
920-788-0200

MADISON, WI  
608-244-0200

[www.reinders.com](http://www.reinders.com)

## TORO GROUNDSMASTER 455-D

- Replace engine oil & filter.
- Replace fuel filter.
- Replace water separator.
- Replace air filter.
- Replace hydro filter.
- Replace rear wheel grease seals, inspect bearings & repack.
- Replace coolant & clean radiator fins.
- Replace blades.
- Test battery, clean battery terminals.
- Test charging system.
- Inspect all belts & adjust as required.
- Inspect all hoses.
- Adjust parking brake.
- Check neutral point for creep & adjust if needed.
- Inspect all safety switches (replace any non-working switches at additional charge - mandatory).
- Inspect for fluid leaks.
- Inspect cutting deck for worn rollers, casters, & spindles.
- Check tire pressure & adjust if needed.
- Lubricate all grease fittings.
- Change cutter deck gearbox oil.
- Adjust air gap on deck clutches.
- Change transaxle fluids.
- Check timing belt.
- Inspect 4WD for leaks & pivot play.
- Replace rear axle fluid in 4WD & steering knuckles.
- Check couplers from engine to hydrostat.

### Recommended Services Done by Request at Additional Cost

- Perform compression test
- Recondition radiator – 1,000 hour intervals
- Send injectors out for calibration – 1,000 hour intervals
- Replace PTO and deck belts – 1,000 hour intervals
- Replace hydro oil – 800 hour intervals
- Replace timing belt – 1,000 hour intervals

*Please notify us ahead of time of any specific problems you're having with your unit.*

*Based on all inspections, if additional work is required, you will be notified with a repair cost estimate.*

**5.5 hours plus parts & lubricants**

## TORO COMMERCIAL MID-SIZE WALK ROTARIES

- Replace engine oil.
- Replace air filter.
- Replace spark plug, points, & condenser (if applicable).
- Replace fuel filter.
- Adjust carb for high/low idle to RPM specifications.
- Check drive belts.
- Check all drive linkage for proper operation.
- Adjust cutting unit drive belt tension.
- Replace blades.
- Inspect caster wheels & bearings.
- Check tire pressure & adjust if needed.
- Test charging system (specific units).
- Adjust PTO clutch air gap.
- Lubricate all grease fittings.
- Inspect spindle bearings - for free play.
- Inspect all safety switches (replace any non-working switches at additional charge - mandatory).

*Based on all inspections, if additional work is required, you will be notified with a repair cost estimate.*

**3.5 hours plus parts & lubricants**



**TAKE ADVANTAGE OF THE REINDERS WINTER SERVICE PROGRAM AND RECEIVE TERMS OF MARCH 31, 2012 INVOICING AND 15% OFF LABOR FOR THIS AND ANY OTHER REPAIRS.**



**Reinders**  
Solutions & Supplies  
for the Green Industry

CHICAGO, IL  
1-866-655-8335  
847-678-5555

MILWAUKEE, WI  
1-800-785-3307  
262-786-3307

APPLETON, WI  
920-788-0200

MADISON, WI  
608-244-0200

[www.reinders.com](http://www.reinders.com)

# TORO GROUNDMASTER 580-D, 5900 AND 5910



- Replace engine oil & filter.
- Replace air filter.
- Replace hydro filters.
- Replace fuel filter.
- Replace water separator.
- Check engine & drive train for leaks.
- Inspect deck belts, spindles, blades, and idlers.
- Check steering & lift cylinders for leaks.
- Inspect driveshaft U-joints.
- Check rear axle pivot pin & bushings for wear.
- Check deck lift arm pivot pins, bushings, & ball joints.
- Check glow plug operation (if applicable).
- Check engine RPM's & adjust if needed.
- Check cooling system (pressurize system, check air flow, replace coolant).
- Check engine belts.
- Check charging system.
- Check batteries (load test), clean battery terminals.
- Check high-speed range operation.
- Check parking brake & adjust if needed.
- Inspect all safety switches (replace any non-working switches at additional charge – mandatory).
- Check traction pedal operation, check neutral on hydro.
- Adjust engine valves, replace valve cover gasket.
- Replace planetary gear lube.
- Remove rear wheels, replace seals, & repack bearings.
- Check tire pressure & adjust if needed.
- Lubricate all grease fittings.

## Recommended Services Done by Request at Additional Cost

- Perform compression test
- Replace brake fluid – 1,000 hour intervals
- Replace hydro oil and clean screen – 800 hour intervals
- Send injectors out for calibration – 1,000 hour intervals
- Recondition radiator – 1,000 hour intervals

*Please notify us ahead of time of any specific problems you're having with your unit.*

*Based on all inspections, if additional work is required, you will be notified with a repair cost estimate.*

**8 hours plus parts & lubricants  
(4WD units & units w/cabs or other accessories will be more)**



**TAKE ADVANTAGE OF THE REINDERS WINTER SERVICE PROGRAM AND RECEIVE TERMS OF MARCH 31, 2012 INVOICING AND 15% OFF LABOR FOR THIS AND ANY OTHER REPAIRS.**



**Reinders**  
Solutions & Supplies  
for the Green Industry

CHICAGO, IL  
1-866-655-8335  
847-678-5555

MILWAUKEE, WI  
1-800-785-3307  
262-786-3307

APPLETON, WI  
920-788-0200

MADISON, WI  
608-244-0200

[www.reinders.com](http://www.reinders.com)

# TORO LIGHTWEIGHT FAIRWAY MOWER



- Replace engine oil & filter.
- Adjust valve clearances & install new valve cover gasket.
- Replace fuel filters.
- Adjust maximum & low engine speed.
- Load test battery, clean battery cables, check electrolyte level - adjust as needed.
- Test alternator output.
- Inspect operation of all gauges, indicator lights, & safety switches (replace any non-working switches at additional charge - mandatory).
- Replace hydro oil filter (change oil or adjust level if needed).
- Inspect all hydro hoses & fittings for wear, clean oil cooler.
- Inspect traction friction wheel.
- Adjust traction linkage for neutral.
- Inspect hydro pump, hydrostatic, & reel motors for leaks.
- Clean & adjust brakes & brake cables, inspect parking brake for proper operation, inspect axle bearings for play.
- Inspect bushings in pull frame.
- Remove the rear wheel bearings, clean & repack, install new grease seals, & reinstall.
- Torque all wheel fasteners.
- Check tire pressure & adjust if needed.
- Lubricate all grease fittings.
- Test glow plug operation.

## Recommended Services Done by Request at Additional Cost

- Perform compression test
- Torque cylinder head - 500 hour intervals
- Send injectors out for calibration - 1,000 hour intervals
- Recondition radiator - 1,000 hour intervals
- Adjust valves - 800 hour intervals

*Please notify us ahead of time of any specific problems you're having with your unit.*

*Based on all inspections, if additional work is required, you will be notified with a repair cost estimate.*

**5.5 hours plus parts & lubricants (Reels - call)**



**TAKE ADVANTAGE OF THE REINDERS WINTER SERVICE PROGRAM AND RECEIVE TERMS OF MARCH 31, 2012 INVOICING AND 15% OFF LABOR FOR THIS AND ANY OTHER REPAIRS.**



**Reinders**  
Solutions & Supplies  
for the Green Industry

CHICAGO, IL  
1-866-655-8335  
847-678-5555

MILWAUKEE, WI  
1-800-785-3307  
262-786-3307


APPLETON, WI  
920-788-0200

MADISON, WI  
608-244-0200

[www.reinders.com](http://www.reinders.com)

# TORO GREENSMaster/TRIPLEX GREENSMOWERS

- Replace engine oil and filter.
- Replace air filter.
- Remove debris from around exterior of the cylinder fins & intake air screen.
- Replace spark plugs, breaker points, & condenser (if applicable).
- Replace fuel filter or clean sediment bowl, inspect all fuel lines.
- Adjust carb idle, check & set high/low RPM's.
- Load test battery, clean battery cables, inspect electrolyte level, & adjust as needed.
- Check charging system.
- Inspect operation of all gauges, indicator lights, & safety switches (replace any non-working switches at additional charge - mandatory).
- Replace hydro oil filter (change oil if needed).
- Inspect hydro hoses & fittings for leaks.
- Check mow detent, lift detent, & pedal height.
- Check operation of traction linkage.
- Clean & adjust brakes, inspect parking brake for proper operation.



- Inspect pull frame for correct alignment.
- Inspect pull frame & pull arm bushings.
- Adjust steering cables (if applicable).
- Torque all wheel fasteners.
- Check tire pressure and adjust if needed.
- Lubricate all grease fittings.
- Inspect lift system bushing for wear.

## Recommended Services Done by Request at Additional Cost

- Perform compression test

*Please notify us ahead of time of any specific problems you're having with your unit.*

*Based on all inspections, if additional work is required, you will be notified with a repair cost estimate.*

**4.25 hours plus parts & lubricants (Reels – call)**



**TAKE ADVANTAGE OF THE REINDERS WINTER SERVICE PROGRAM AND RECEIVE TERMS OF MARCH 31, 2012 INVOICING AND 15% OFF LABOR FOR THIS AND ANY OTHER REPAIRS.**



**Reinders**  
Solutions & Supplies  
for the Green Industry

CHICAGO, IL  
1-866-655-8335  
847-678-5555

MILWAUKEE, WI  
1-800-785-3307  
262-786-3307

APPLETON, WI  
920-788-0200

MADISON, WI  
608-244-0200

[www.reinders.com](http://www.reinders.com)

## TORO WALKING GREENSMOWERS

- Replace spark plug.
- Replace engine oil and filter.
- Inspect for worn reel bearings.
- Inspect & adjust carb & all cables.
- Inspect & adjust all belts.
- Inspect for worn roller bearings.
- Lubricate all grease fittings.
- Check tire pressure on pneumatic style wheels and adjust if needed.
- Inspect operation of all gauges & safety switches (replace any non-working switches at additional charge – mandatory).
- Change gearbox fluid (Flex 21 model).
- Check rear drum for play.



*Please notify us ahead of time of any specific problems you're having with your unit.*

### Recommended Services Done by Request at Additional Cost

- Perform compression test

*Based on all inspections, if additional work is required, you will be notified with a repair cost estimate.*

**1.5 hours plus parts & lubricants (Reels – call, Groomer repair work is additional)**

## TORO HEAVY DUTY WORKMAN

- Check cable adjustment.
- Replace transaxle filter.
- Check transaxle oil & change (if needed).
- Change engine oil & filter.
- Replace spark plug (if applicable).
- Check battery & cable connections.
- Service air cleaner.
- Lube all grease fittings.
- Inspect condition & wear of tires.
- Check front differential oil level & change (if needed - 4WD).
- Inspect cooling system hoses.
- Check alternator & fan belts.
- Check front axle CV boot joint (4WD).
- Inspect service & parking brake.
- Check front wheel alignment.
- Replace fuel/water separator filter.
- Check & pack front wheel bearings (if needed).
- Clean radiator exterior & inspect all hoses for wear.
- Change coolant & fill to proper level.
- Check charging system.
- Check engine mounts.

### Recommended Services Done by Request at Additional Cost

- Perform compression test (Diesel - 1 hour, Gas - 1/2 hour)

**3 hours plus parts & lubricants**



**TAKE ADVANTAGE OF THE REINDERS WINTER SERVICE PROGRAM AND RECEIVE TERMS OF MARCH 31, 2012 INVOICING AND 15% OFF LABOR FOR THIS AND ANY OTHER REPAIRS.**



**Reinders**  
Solutions & Supplies  
for the Green Industry

CHICAGO, IL  
1-866-655-8335  
847-678-5555

MILWAUKEE, WI  
1-800-785-3307  
262-786-3307

APPLETON, WI  
920-788-0200

MADISON, WI  
608-244-0200

[www.reinders.com](http://www.reinders.com)

# TORO ZTR MOWER

- Replace engine oil and filter.
- Change & gap spark plug.
- Replace air filter.
- Replace fuel filter.
- Clean any grass & oil build-up off shrouds & engine cooling fins.
- Inspect all cable linkages, lube & adjust.
- Inspect all mower spindles, check bearing for wear, & lube spindle bearings.
- Check transmission drive belt.
- Check all drive linkage & neutral for proper operation.
- Adjust cutting unit drive belt tension.
- Replace blades.
- Test electrical system for proper operation including battery test.
- Check governor & set RPM to factory specification.
- Replace hydro filter & check system for leaks.
- Inspect caster wheel bushings & bearings for wear.
- Check tire pressure and adjust if needed.
- Inspect all safety switches (replace any non-working switches at additional charge - mandatory).
- Check for missing or worn deck anti-scalp wheels.
- Lubricate all grease fittings.
- Adjust parking brake.
- Check for engine oil leaks.



## Recommended Services Done by Request at Additional Cost

- Perform compression test

*If ZTR unit has a vacuum system there is an additional 1 hour labor charge plus parts.*

*Please notify us ahead of time of any specific problems you're having with your unit.*

*Based on all inspections, if additional work is required, you will be notified with a repair cost estimate.*

**1.7 hours plus parts & lubricants**



**TAKE ADVANTAGE OF THE REINDERS WINTER SERVICE PROGRAM AND RECEIVE TERMS OF MARCH 31, 2012 INVOICING AND 15% OFF LABOR FOR THIS AND ANY OTHER REPAIRS.**



**Reinders**  
Solutions & Supplies  
for the Green Industry

CHICAGO, IL  
1-866-655-8335  
847-678-5555

MILWAUKEE, WI  
1-800-785-3307  
262-786-3307

APPLETON, WI  
920-788-0200

MADISON, WI  
608-244-0200

[www.reinders.com](http://www.reinders.com)

## SHARPENING RATES FOR THE 2011-2012 SEASON

Prices listed are for sharpening reels & bedknives only. Other repairs and all parts used will be extra.  
Gang mowers must be removed from the frames.

2011-2012 Sharpening Rates\* - Price includes spin grind and relief grind if needed.

Toro Greensmowers and Lightweight Fairway Units .....	\$119.99 per reel
Toro RM3100-D, RM2000, 4000 and 6000 Series.....	\$139.99 per reel
Toro Gang Mowers .....	\$169.99 per reel
Other cutting units .....	CALL

Sharpening rates for the cutting units include:

- Labor for turning or replacing the bed knife & sharpening.
- Adjusting reel bearing preload and check freeplay.
- Adjusting single point adjuster, for proper orientation.
- Replacement of bedknife and screws.
- Changing oil in gang mower cases will be an additional \$49.99.
- Additional attachments extra.
- Check and fill gearcase lubrication level.
- Spin grind reel & relief grind if needed.

Please answer the following prior to cutting unit sharpening:

- What is the cutting unit application (tees, fairway, greens, etc.)?
- What height-of-cut should the cutting units be set for?
- Do you want the reel bearings replaced as part of routine maintenance on reels?  
There will be an additional charge for this.

### NOTE

- All reels are roller-mounted when ground, and rollers must not have any freeplay. They will be repaired unless you request not to do so.
- Bent or broken reel blades cannot be relief-ground.

\* All parts and lubricants are extra. If additional work is required, you will be notified with a repair cost estimate. Repairs may be required in order to properly sharpen cutting units.

## OVERHAUL RATES FOR THE 2011-2012 SEASON

Toro Greensmowers and Lightweight Fairway Units .....	\$99.99 each
Toro RM2000, 3100, 4000 and 6000 Series .....	\$139.99 each
Toro Gang Mowers .....	\$167.99 each
Toro Rollers .....	\$44.99 each

## ADDITIONAL TORO EQUIPMENT SERVICED

- Reelmaster 3100, 4000 & 6000 Series
- Groundsmaster 450, 3500-D, 4500-D & 4700-D
- Light & Mid-Duty Workman
- Sand Pro/Infield Pro
- Multi Pro-Sprayers

Repairs will be done on a time and material basis for preventative and necessary repairs requested on the machines listed above. Estimates will be given prior to any repair. You receive a **15% discount** off the regular hourly rate.



**TAKE ADVANTAGE OF THE REINDERS WINTER SERVICE PROGRAM AND RECEIVE TERMS OF MARCH 31, 2012 INVOICING AND 15% OFF LABOR FOR THIS AND ANY OTHER REPAIRS.**



**Reinders**  
Solutions & Supplies  
for the Green Industry

CHICAGO, IL  
1-866-655-8335  
847-678-5555

MILWAUKEE, WI  
1-800-785-3307  
262-786-3307

APPLETON, WI  
920-788-0200

MADISON, WI  
608-244-0200

www.reinders.com