

# INSTALLATION INSTRUCTIONS

## Surface Mount Indicator Light

2501 / 2511 / 2541 / 2571 / 2591

# WAC LIGHTING

### WARNING

IMPORTANT: NEVER attempt to do any work without shutting off the electricity.

1. Read all instructions before installing.
2. System is intended for installation by a qualified electrician in accordance with the National Electrical Code and local regulations.
3. Place the wall switch in the "OFF" position.
4. Go to the main fuse box, or circuit breaker. Unscrew the fuse(s) or switch "OFF" the circuit breaker switch(es) that control the power to the space that you are working on.
5. Risk of electric shock. Install all luminaires 10 feet (3.05m) or more from a pool, spa or fountain.

### CAUTION

- All parts must be used as indicated in these instructions. Do not substitute any parts, leave parts out, or use any parts that are worn out or broken. Failure to follow this instruction may invalidate the UL listing of this fixture.

### AVERTISSEMENT

IMPORTANT: Coupez l'électricité avant TOUTE manipulation.

- Lisez toutes les instructions avant d'installer.
- Système est destiné à être installé par un électricien qualifié en conformité avec le code national de l'électricité et les règlements locaux.
- Placez l'interrupteur mural en position d'arrêt (« OFF »).
- Toujours mettre le fusible ou le disjoncteur en position arrêt dans la pièce ou des travaux électriques sont prévus

### MISE EN GARDE

- Toutes les pièces doivent être utilisées tel qu'il est indiqué dans ces instructions. Ne remplacez pas les pièces, n'en laissez pas de côté et ne les utilisez pas si elles sont usées ou brisées. Le non-respect de ces instructions peut annuler l'homologation UL du luminaire.

### ADVERTENCIA


IMPORTANTE: NUNCA intente hacer trabajos sin desconectar el suministro eléctrico.

- Lea y comprenda todas las instrucciones e ilustraciones por completo antes de proceder con el ensamblaje e instalación de esta lámpara.
- Sistema está diseñado para ser instalado por un electricista calificado, de acuerdo con el código eléctrico nacional y las normas locales.
- Coloque el interruptor de la pared en la posición "OFF" (APAGADO).
- Diríjase a la caja de fusibles o a la caja del interruptor de circuito principal en su hogar. Coloque el interruptor de alimentación principal en la posición "OFF" (APAGADO).


### PRECAUCIÓN

- Todas las piezas deben usarse como lo indican estas instrucciones. No reemplace las piezas, noomita piezas durante la instalación ni utilice piezas gastadas o rotas. El incumplimiento de esta indicación podría invalidar la calificación UL esta lámpara.


### THE INSTRUCTIONS APPLY TO THE MODEL(S) BELOW:




2541




2501



2511



2571



2591

waclighting.com  
Phone (800) 526.2588  
Fax (800) 526.2585

Headquarters/Eastern Distribution Center  
44 Harbor Park Drive  
Port Washington, NY 11050


Central Distribution Center  
1600 Distribution Ct  
Lithia Springs, GA 30122

Western Distribution Center  
1750 Archibald Avenue  
Ontario, CA 91760


INSTALLATION INSTRUCTIONS  
**Surface Mount Indicator Light**  
2501 / 2511 / 2541 / 2571 / 2591

WAC LIGHTING


**INSTALLATION ACCESSORIES**



Wire Nut  
Qty: 2 pcs  
7EAC112201P3




Hex Key  
Qty: 1 pcs  
7MPE155003



Mounting Hardware  
Qty: 2 pcs/each

**INSTALLATION (CONCRETE/WOOD/WALL):**

1. Disassemble the fixture mounting base bracket from the fixture assembly.
2. Take off the fixture cap from the fixture body by unscrewing the locking set screw.
3. Mark the fixture mounting location on the concrete/wood floor using the fixture body.
4. Drill a through hole to allow fixture lead wire to exit the concrete/wood floor or use the lead wire side exit. Drill anchor holes for plastic anchors (for concrete installation).
5. Use #8 tapping screws (and plastic anchors) to mount the fixture body.
6. Mount the fixture cap back to the fixture body by snapping it into the slot.
7. Lock the fixture cap by tightening the locking set screw on the side.



wacighting.com  
Phone (800) 526.2588  
Fax (800) 526.2585

Headquarters/Eastern Distribution Center  
44 Harbor Park Drive  
Port Washington, NY 11050

Central Distribution Center  
1600 Distribution Ct  
Lithia Springs, GA 30122

Western Distribution Center  
1750 Archibald Avenue  
Ontario, CA 91760