


OSMAC G3 - Power Supply



#	Description
	102-0645 Power Supply Assy.
1	118-4269 Cover, Power Supply Housing
2	118-4268 Cover, Power Supply Terminal
3	118-4270 Bottom, Power Supply Housing
4	360-0498 Screw, Machine, 8-32 x 1/4, PHPH, SST

#	Description
5	363-3981 Terminal Block, 3-Position, 6 AWG
6	118-0538SK Toro Transient Filter, TTF
7	363-8690 Screw, Machine, 6-32 x 3/8, PHPH, STL
8	363-3361 Switch, Circuit Breaker, 1.5A
9	360-0750 Holder, Fuse
10	363-2497 Fuse, 3.2 Amp, Distribution
11	363-5270 Circuit Breaker, 4.0A
12	102-0409 Transformer Assembly
13	3-1453 Screw, Machine, 10-32 x 3/8, PHPH, SS